### DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection Bay Area Branch 690 Walnut Ave.St. 150

Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 70.28

## WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-005161 Address: 333 Burma Road **Date Inspected:** 05-Jan-2009

City: Oakland, CA 94607

**Project Name:** SAS Superstructure **OSM Arrival Time:** 830 **OSM Departure Time:** 1830 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Japan Steel Works **Location:** Muroran, Japan

**CWI Name: CWI Present:** Yes Chung Kuan No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No Weld Procedures Followed: Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes No N/A **Delayed / Cancelled:** 

34-0006 **Bridge No: Component:** Tower, Jacking and Deviation Saddles

### **Summary of Items Observed:**

Steel Structure Welding Shop:

Tower Saddle Steel Structure T1-3: Caltrans Quality Assurance Inspector (QAI) representative observed Japan Steel Works (JSW) welders in process of grinding weld profiles of weld numbers 9Y-11V (3-2) (3-3) and 9Y-12V (3-2) (3-3) for MT test purpose. Based on Caltrans QA Inspector observation, no discrepancies were noted. W2E3 West Deviation Saddle Steel Structure: Caltrans QAI representative observed a JSW welder perform a SMAW welding on temporary reinforce supports around all the rib plates and stem plate. The temporary reinforce supports are to prevent distortion during the production welding. The proper filler metal used for SMAW welding is Hoballoy 9018-M with 5mm diameter electrode made by Hobart Brothers, USA. The SMAW welding process and parameters have been monitored and recorded by CWI inspector Mr. Chung Kuan.

#### Casting Shop:

The NDT test schedule on casting portion W2W1, T1-2 and T1-3 has been cancelled for today.

## **Summary of Conversations:**

As noted within the report.

#### **Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Nina Choy (510)385-5910, who represents the Office of Structural Materials for your project.

# WELDING INSPECTION REPORT

(Continued Page 2 of 2)

**Inspected By:** Pau,Wai Quality Assurance Inspector **Reviewed By:** Lanz,Joe QA Reviewer